



RH TERRELL REC LEAD WATER TEST RESULTS

May 16th, 2016

elev★te

	Building Location	Sample Collected Date	Water Source ID	Device Type	Floor	Device Location	1st Draw - Sample ID	Final Result - 1st Draw (ug/L)	2nd Draw - Sample ID	Final Result - 2nd Draw (ug/L)	Remediation	Retest Date	Retest 1st Draw	Retest 2nd Draw
1	RH TERRELL RECREATION CENTER	5/28/2016	WS- 006160	Cooler	1	In rec center lobby across from elevator Left High	WT-042916-6177- A	< 1	WT-042916-6177- B	< 1				
2	RH TERRELL RECREATION CENTER	5/28/2016	WS- 006161	Cooler	1	In rec center lobby across from elevator Right Low	WT-042916-6178- A	< 1	WT-042916-6178- B	< 1				

Footnotes:

A - First draw sample is collected after the plumbing system has not been used for at least 6 hours.

B - Second draw sample is collected after a 60 second flush at that device after the first draw.